

Collision Course (Titanic)

Sinking of the Titanic

collision by a distance of about 4 feet (1.2 m). The incident, as well as a subsequent stop to offload a few stragglers by tug, delayed the Titanic's - RMS Titanic sank on 15 April 1912 in the North Atlantic Ocean. The largest ocean liner in service at the time, Titanic was four days into her maiden voyage from Southampton, England, to New York City, United States, with an estimated 2,224 people on board when she struck an iceberg at 23:40 (ship's time) on 14 April. She sank two hours and forty minutes later at 02:20 ship's time (05:18 GMT) on 15 April, resulting in the deaths of up to 1,635 people, making it one of the deadliest peacetime maritime disasters in history.

Titanic received six warnings of sea ice on 14 April, but was travelling at a speed of roughly 22 knots (41 km/h) when her lookouts sighted the iceberg. Unable to turn quickly enough, the ship suffered a glancing blow that buckled the steel plates covering her starboard side and opened six of her sixteen compartments to the sea. Titanic had been designed to stay afloat with up to four of her forward compartments flooded, and the crew used distress flares and radio (wireless) messages to attract help as the passengers were put into lifeboats.

In accordance with existing practice, the Titanic's lifeboat system was designed to ferry passengers to nearby rescue vessels, not to hold everyone on board simultaneously; therefore, with the ship sinking rapidly and help still hours away, there was no safe refuge for many of the passengers and crew, as the ship was equipped with only twenty lifeboats, including four collapsible lifeboats. Poor preparation for and management of the evacuation meant many boats were launched before they were completely full.

Titanic sank with over a thousand passengers and crew still on board. Almost all of those who ended up in the water died within minutes due to the effects of cold shock. RMS Carpathia arrived about an hour and a half after the sinking and rescued all of the 710 survivors by 09:15 on 15 April. The disaster shocked the world and caused widespread outrage over the lack of lifeboats, lax regulations, and the unequal treatment of third-class passengers during the evacuation. Subsequent inquiries recommended sweeping changes to maritime regulations, leading to the establishment in 1914 of the International Convention for the Safety of Life at Sea (SOLAS) which still governs maritime safety today.

Olympic–Hawke collision

and maiden voyage of Olympic's sister ship, RMS Titanic. Due to the financial blow suffered from collision, the White Star Line was eager to get Olympic - On 20 September 1911, while travelling down the Solent, the Royal Navy cruiser HMS Hawke collided with the White Star ocean liner RMS Olympic.

Olympic was, at the time, the world's largest ocean liner and was undergoing what would have been her fifth voyage. In the course of the collision, Hawke lost her inverted bow, which was replaced by a straight bow. The subsequent trial pronounced Hawke to be free from any blame. During the trial, a theory was advanced that the large amount of water displaced by Olympic had generated a suction that had drawn Hawke off course, causing the Olympic's voyage to be delayed. The White Star Line also lost on appeal.

The collision had the consequence of delaying the completion and maiden voyage of Olympic's sister ship, RMS Titanic. Due to the financial blow suffered from collision, the White Star Line was eager to get Olympic back into service and diverted workers from the still-under-construction Titanic to help with the

repairs.

Wreck of the Titanic

of items spilled from the ship as she sank. The Titanic sank on April 15, 1912, following her collision with an iceberg during her maiden voyage. Numerous - The wreck of British ocean liner RMS Titanic lies at a depth of about 12,500 feet (3,800 metres; 2,100 fathoms), about 325 nautical miles (600 kilometres) south-southeast off the coast of Newfoundland. It lies in two main pieces about 2,000 feet (600 m) apart. The bow is still recognisable with many preserved interiors, despite deterioration and damage sustained by hitting the sea floor; in contrast, the stern is heavily damaged. The debris field around the wreck contains hundreds of thousands of items spilled from the ship as she sank.

The Titanic sank on April 15, 1912, following her collision with an iceberg during her maiden voyage. Numerous expeditions unsuccessfully tried using sonar to map the seabed in the hope of finding the wreckage. In 1985, the wreck was located by a joint French–American expedition led by Jean-Louis Michel of IFREMER and Robert Ballard of the Woods Hole Oceanographic Institution, originally on a mission to find two nuclear Cold War submarines. The wreck has been the focus of intense interest and has been visited by numerous tourist and scientific expeditions, including by the submersible Titan, which imploded near the wreck in June 2023, killing all five aboard.

Controversial salvage operations have recovered thousands of items, many of which have been conserved and put on public display. Many schemes have been proposed to raise the wreck, including filling it with ping-pong balls, injecting it with 180,000 tons of Vaseline, or using half a million tons of liquid nitrogen to encase it in an iceberg that would float to the surface. However, the wreck is too fragile to be raised and is protected by a UNESCO convention.

Titanic

RMS Titanic was a British ocean liner that sank in the early hours of 15 April 1912 as a result of striking an iceberg on her maiden voyage from Southampton - RMS Titanic was a British ocean liner that sank in the early hours of 15 April 1912 as a result of striking an iceberg on her maiden voyage from Southampton, England, to New York City, United States. Of the estimated 2,224 passengers and crew aboard, approximately 1,500 died (estimates vary), making the incident one of the deadliest peacetime sinkings of a single ship. Titanic, operated by White Star Line, carried some of the wealthiest people in the world, as well as hundreds of emigrants from the British Isles, Scandinavia, and elsewhere in Europe who were seeking a new life in the United States and Canada. The disaster drew public attention, spurred major changes in maritime safety regulations, and inspired a lasting legacy in popular culture. It was the second time White Star Line had lost a ship on her maiden voyage, the first being RMS Tayleur in 1854.

Titanic was the largest ship afloat upon entering service and the second of three Olympic-class ocean liners built for White Star Line. The ship was built by the Harland and Wolff shipbuilding company in Belfast. Thomas Andrews Jr., the chief naval architect of the shipyard, died in the disaster. Titanic was under the command of Captain Edward John Smith, who went down with the ship. J. Bruce Ismay, White Star Line's chairman, managed to get into a lifeboat and survived.

The first-class accommodations were designed to be the pinnacle of comfort and luxury. They included a gymnasium, swimming pool, smoking rooms, fine restaurants and cafes, a Victorian-style Turkish bath, and hundreds of opulent cabins. A high-powered radiotelegraph transmitter was available to send passenger "marconigrams" and for the ship's operational use. Titanic had advanced safety features, such as watertight compartments and remotely activated watertight doors, which contributed to the ship's reputation as

"unsinkable".

Titanic was equipped with sixteen lifeboat davits, each capable of lowering three lifeboats, for a total capacity of 48 boats. Despite this capacity, the ship was scantily equipped with a total of only twenty lifeboats. Fourteen of these were regular lifeboats, two were cutter lifeboats, and four were collapsible and proved difficult to launch while the ship was sinking. Together, the lifeboats could hold 1,178 people—roughly half the number of passengers on board, and a third of the number of passengers the ship could have carried at full capacity (a number consistent with the maritime safety regulations of the era). The British Board of Trade's regulations required fourteen lifeboats for a ship of 10,000 tonnes. Titanic carried six more than required, allowing 338 extra people room in lifeboats. When the ship sank, the lifeboats that had been lowered were only filled up to an average of 60%.

RMS Olympic

stoker Arthur John Priest, survived not only the collision with Hawke but also the later sinking of Titanic and the 1916 sinking of Britannic, the third ship - RMS Olympic was a British ocean liner and the lead ship of the White Star Line's trio of Olympic-class liners. Olympic had a career spanning 24 years from 1911 to 1935, in contrast to her short-lived sister ships, RMS Titanic and the Royal Navy hospital ship HMHS Britannic. This included service as a troopship with the name HMT Olympic during the First World War, which gained her the nickname "Old Reliable", and during which she rammed and sank the U-boat U-103. She returned to civilian service after the war and served successfully as an ocean liner throughout the 1920s and into the first half of the 1930s, although increased competition, and the slump in trade during the Great Depression after 1930, made her operation increasingly unprofitable. Olympic was withdrawn from service on 12 April 1935, and later sold for scrap, which was completed by 1939.

Olympic was the largest ocean liner in the world for two periods during 1910–13, interrupted only by the brief service life (six-day maiden voyage in April 1912) of the slightly larger Titanic, which had the same dimensions but higher gross register tonnage, before the German SS Imperator went into service in June 1913. Olympic also held the title of the largest British-built liner until RMS Queen Mary was launched in 1934, interrupted only by the short career of Titanic; Britannic, intended as a liner, instead served as a Royal Navy hospital ship for her 11-month life (December 1915 to November 1916), sinking when she hit a mine.

Titanic (1997 film)

Titanic is a 1997 American epic romantic disaster film written and directed by James Cameron. Incorporating both historical and fictionalized aspects - Titanic is a 1997 American epic romantic disaster film written and directed by James Cameron. Incorporating both historical and fictionalized aspects, it is based on accounts of the sinking of RMS Titanic in 1912. The film stars Leonardo DiCaprio and Kate Winslet as members of different social classes who fall in love during the ship's maiden voyage. The film also features an ensemble cast of Billy Zane, Kathy Bates, Frances Fisher, Bernard Hill, Jonathan Hyde, Danny Nucci, David Warner, and Bill Paxton.

Cameron's inspiration for the film came from his fascination with shipwrecks. He felt a love story interspersed with human loss would be essential to convey the emotional impact of the disaster. Production began on September 1, 1995, when Cameron shot footage of the Titanic wreck. The modern scenes on the research vessel were shot on board the Akademik Mstislav Keldysh, which Cameron had used as a base when filming the wreck. Scale models, computer-generated imagery, and a reconstruction of the Titanic built at Baja Studios were used to recreate the sinking. The film was initially in development at 20th Century Fox, but a mounting budget and being behind schedule resulted in Fox asking Paramount Pictures for financial help; Paramount handled distribution in the United States and Canada, while Fox released the film in other territories. Titanic was the most expensive film ever made at the time, with a production budget of \$200

million. Filming took place from July 1996 to March 1997.

Titanic premiered at the Tokyo International Film Festival on November 1, 1997, and was released in the United States on December 19. It was praised for its visual effects, performances (particularly those of DiCaprio, Winslet, and Gloria Stuart), production values, direction, score, cinematography, story, and emotional depth. Among other awards, it was nominated for 14 Academy Awards and won a record-tying 11, including Best Picture and Best Director, tying Ben-Hur (1959) for the most Academy Awards won by a film. With an initial worldwide gross of over \$1.84 billion, Titanic was the first film to reach the billion-dollar mark. It was the highest-grossing film of all time until Cameron's next film, Avatar (2009), surpassed it in 2010. Income from the initial theatrical release, retail video, and soundtrack sales and US broadcast rights exceeded \$3.2 billion. A number of re-releases have pushed the film's worldwide theatrical total to \$2.264 billion, making it the second film to gross more than \$2 billion worldwide after Avatar. The Library of Congress selected it for preservation in the United States National Film Registry for being "culturally, historically, or aesthetically significant" in 2017.

Millvina Dean

Titanic; her mother died on 16 September 1975, aged 96; and her brother died on 14 April 1992, age 81, the 80th anniversary of the iceberg collision. - Eliza Gladys Dean (2 February 1912 – 31 May 2009), known as Millvina Dean, was a British civil servant, cartographer, and the last living survivor of the sinking of the RMS Titanic on 15 April 1912. At two months old, she was also the youngest passenger aboard.

Titanic navigation bridge

On the Titanic, the navigation bridge (or command bridge) was a superstructure where the ship's command was exercised. From this location, the officer on watch determined the ship's geographical position, gave all orders regarding navigation and speed, and received information about everything happening on board.

The bridge was composed of various compartments: a navigation shelter where watch was kept, and the wheelhouse where a wheel was located, known as the helm in maritime language, which steered the rudder and transmitted orders to the engines, also called a chadburn. On either side to starboard and port of the navigation shelter, two exterior wings allowed for maneuvers. There was also a chart room and the captain's watch room. The bridge was also connected to the officers' cabins, which varied in comfort according to rank. It was also close to the wireless telegraphy room. Six officers took turns on watch duty on the bridge, accompanied by quartermasters and other members of the deck crew. The second officer and the captain could also be present if the situation so required.

On 14 April 1912, around 11:40 p.m., decisions to attempt to avoid the iceberg were made from the bridge. After the collision, the order to evacuate the ship was also decided on the bridge. Crushed by the fall of the first funnel, then by that of the foremast, little remained of the bridge when the wreckage of the Titanic was discovered in 1985.

Andromeda–Milky Way collision

The Andromeda–Milky Way collision is a galactic collision that may occur in about 4.5 billion years between the two largest galaxies in the Local Group—the Milky Way (which contains the Solar System and Earth) and the Andromeda Galaxy.

The stars involved are sufficiently spaced that it is improbable that any of them would individually collide, though some stars may be ejected.

Lifeboats of the Titanic

Lifeboats played a crucial role during the sinking of the Titanic on 14–15 April 1912. The ship had 20 lifeboats that, in total, could accommodate 1,178 - Lifeboats played a crucial role during the sinking of the Titanic on 14–15 April 1912. The ship had 20 lifeboats that, in total, could accommodate 1,178 people, a little over half of the 2,209 on board the night it sank. 18 lifeboats were used, loading between 11:45 p.m. and 2:05 a.m., though Collapsible Boat A floated off the ship's partially submerged deck and Collapsible Boat B floated away upside down minutes before the ship upended and sank.

Many lifeboats only carried a fraction of their maximum capacity which, depending on type, was 40, 47, or 65 people. There are many versions as to the reasoning behind half-filled lifeboats; these included the order of "women and children first", apprehensions that the lifeboats could buckle under the weight, and the fact that many passengers did not feel safe stepping in a lifeboat hovering 90 feet above the freezing ocean and others refused to leave behind family and friends. As the half-filled boats rowed away from the ship, they were too far away for other passengers to reach, and most lifeboats did not return to the wreck due to a fear of being swamped by drowning victims or the suction of the sinking ship. Only Lifeboats No. 4 and No. 14 returned to retrieve survivors from the water, some of whom later died.

Although the number of lifeboats was insufficient, Titanic complied with maritime safety regulations at the time and even went over regulations by adding four collapsibles. The sinking showed that the regulations were outdated for such large passenger ships. In the event of an emergency, it was not anticipated that all passengers and crew would require evacuation at the same time; it was believed that Titanic could float long enough to allow a transfer of passengers and crew to a rescue vessel.

A total of 1,503 people died when the Titanic sank in the North Atlantic Ocean. Many of them had not made it into a boat. Only 706 people survived in the lifeboats until later that morning when they were rescued by the RMS Carpathia. Those aboard the lifeboats were picked up by Carpathia over the course of 4 hours and 30 minutes, from about 4 a.m. to 8:30 a.m., and 13 of the lifeboats were also taken aboard. The lifeboats were returned to the White Star Line at New York Harbor, as they were the only items of value salvaged from the shipwreck, but subsequently vanished from history over time.

<https://eript-dlab.ptit.edu.vn/=41021345/cdescendz/asuspendh/udeclinep/honda+crv+mechanical+manual.pdf>
<https://eript-dlab.ptit.edu.vn/=55656957/ucontrolg/dcriticises/hdeclinew/toyota+celica+fuel+pump+relay+location+manual.pdf>
<https://eript-dlab.ptit.edu.vn/@80978959/bcontrolp/ecommity/zeffecti/2000+5+9l+dodge+cummins+24v+used+diesel+engines.p>
<https://eript-dlab.ptit.edu.vn/-47469232/fgatherw/gpronouncex/yeffecto/reimagining+india+unlocking+the+potential+of+asias+next+superpower.>
https://eript-dlab.ptit.edu.vn/_38824204/jcontroly/fsuspendg/deffectu/29+note+taking+study+guide+answers.pdf
<https://eript-dlab.ptit.edu.vn/^24328793/vsponsort/ocontaink/feffectd/matlab+solution+manual.pdf>
<https://eript-dlab.ptit.edu.vn/=20047420/kdescendj/bcommittz/feffectt/answers+for+bvs+training+dignity+and+respect.pdf>
<https://eript-dlab.ptit.edu.vn/!35990435/vinterruptp/gsuspendi/bqualifyx/hyundai+backhoe+loader+hb90+hb100+operating+man>
<https://eript-dlab.ptit.edu.vn/@39874871/dfacilitatet/nevaluatea/owonderh/yamaha+xtz750+1991+repair+service+manual.pdf>
<https://eript-dlab.ptit.edu.vn/@39874871/dfacilitatet/nevaluatea/owonderh/yamaha+xtz750+1991+repair+service+manual.pdf>

